


WIRING DIAGRAM:

replacement of Barber-Coleman model DYN1-10850-810 (Terex P/N 70919) engine speed governor controller
 Precision Governors model E-301 (Terex P/N 0270919-1)
 with

PRELIMINARY COPY

LIST



- 48F
- 301F,G
- 407C
- 407B
- 400A
- 401A
- new wire (from 87A on RS1)
- 403A

